



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

May 11, 2007

Supervisor DAZ

Mine Name: Antelope Quarry
Operator Name: Bown Stone Products.

Permit number: S/039/018
Inspection Date: August 30, 2006
Time: 3:30 pm

Inspector(s): Lynn Kunzler, DOGM
Other Participants: Jerome Bown, Matt Bown
Mine Status: Proposed

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

Inspection made at request of operator

Inspection Summary:

The operator has flagged their proposed access road and quarry area (no disturbance to date). Operator is in process of obtaining the reclamation surety and wanted to make sure he had adequate surety for the expected extent of disturbance. A GPS was used to chart the proposed location of the road and to determine the extent of quarry area marked.

Conclusions and Recommendations:

Preliminary results of GPS survey showed that about 2.5 acres would be disturbed (as flagged). The operator will extend the area of the quarry and re-submit the maps to show the increased area. Operator would like to begin operations on this site within the next couple of months.

Continue to monitor this site when in the area.

Inspector's Signature z 14

LK:pb

O:\M039-Sanpete\S0390018-Antelope\inspections\Insp-08302006.doc